



Código : 472813 Uniones de cobre reduccion-1.5/8x 5/8-C



| WROT | | | CONNECTION | | | CAST | | |
|----------------|--------|--------|--------------|--------|------------|------|---|--|
| WC-400R | | | C X C | | | | | |
| WROT ELKHART | | CAST | WROT | | NIBCO | CAST | | |
| 100R | | 4701-R | 600 | | | 601 | | |
| O.D. | Part | Box | Master | Approx | Dimensions | | | |
| 1 | 2 | Qty | Qty | Net Wt | A | B | C | |
| 1/2 x 1/4 | W01021 | 50 | 1.200 | .02 | 3/8 | | | |
| 1/2 x 3/8 | W01019 | 50 | 1.700 | .02 | 7/32 | | | |
| 5/8 x 1/4 | W01027 | 100 | 1.000 | .03 | 23/64 | | | |
| 5/8 x 3/8 | W01025 | 100 | 1.000 | .03 | 19/64 | | | |
| 3/4 x 3/8 | W01031 | 100 | 600 | .04 | 5/16 | | | |
| 3/4 x 1/2 | W01030 | 100 | 600 | .03 | 3/16 | | | |
| 3/4 x 5/8 | W01029 | 100 | 600 | .05 | 1/4 | | | |
| 7/8 x 3/8 | W01038 | 50 | 500 | .06 | 3/8 | | | |
| 7/8 x 1/2 | W01037 | 50 | 500 | .06 | 13/32 | | | |
| 7/8 x 5/8 | W01036 | 25 | 500 | .08 | 19/64 | | | |
| 7/8 x 3/4 | W01035 | 100 | 1.000 | .06 | 13/64 | | | |
| 1 1/8 x 1/2 | W01052 | 25 | 250 | .10 | 15/32 | | | |
| 1 1/8 x 5/8 | W01051 | 25 | 250 | .11 | 13/32 | | | |
| 1 1/8 x 3/4 | W01050 | 25 | 250 | .10 | 23/64 | | | |
| 1 1/8 x 7/8 | W01049 | 25 | 250 | .13 | 11/32 | | | |
| 1 3/8 x 5/8 | W01060 | 10 | 100 | .15 | 17/32 | | | |
| 1 3/8 x 7/8 | W01058 | 10 | 100 | .17 | 13/32 | | | |
| 1 3/8 x 1 1/8 | W01056 | 10 | 100 | .18 | 9/32 | | | |
| 1 5/8 x 5/8 | W01069 | 10 | 100 | .23 | 25/32 | | | |
| 1 5/8 x 7/8 | W01067 | 10 | 100 | .22 | 19/32 | | | |
| 1 5/8 x 1 1/8 | W01065 | 10 | 100 | .24 | 15/32 | | | |
| 1 5/8 x 1 3/8 | W01064 | 10 | 100 | .24 | 5/16 | | | |
| 2 1/8 x 5/8 | W01079 | 1 | 75 | .40 | 1 3/32 | | | |
| 2 1/8 x 7/8 | W01077 | 1 | 100 | .39 | 29/32 | | | |
| 2 1/8 x 1 1/8 | W01075 | 1 | 100 | .38 | 13/16 | | | |
| 2 1/8 x 1 3/8 | W01074 | 1 | 100 | .41 | 35/64 | | | |
| 2 1/8 x 1 5/8 | W01073 | 1 | 100 | .39 | 15/32 | | | |